

NOTICE OF SPCC INSPECTION

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 6

	ector (Print Name & Sign) m McKa, Da moky iase nation	Inspection Number 58cc 02-2016 cc 16
Facility Name Joag e Tank Balley	Facility Address	Facility Type
Facility Phone 918 - 846 - 2293 (b) (6)	Facility Email	Facility Fax 918 - 846 2205
Prevention regulations found at 40 C F R Parto reviewing and obtaining copies of documentaking photographs or video collecting sample	ine compliance with Section 311 of the Clean Water Act (the Act.) 3.112 (the Regulations.) The scope of the inspection and plan review its and records. Interviewing facility personnel a physical inspection of and other activities necessary to determine compliance with the Act. (Notice.) carefully Note that any deficiencies identified by the inspec	process may include but is not limited if the facility (including process areas) and the regulations

Please be advised that any noncompliance with the Regulations may constitute a violation under the Act for which penalties or other relief may be sought Penalties may be assessed upon subsequent findings by the Administrator or a court that the facility has violated the Act and/or the regulations. The United States Environmental Protection Agency (EPA) reserves its right to initiate an enforcement action under the Act and any other applicable law to seek penalties and other appropriate relief for any violation of the Act the Regulations or such other laws. This Notice and other relevant information will be reviewed by appropriate EPA personnel to determine if any deficiencies identified in such review constitute violations of the Act and the Regulations and whether an enforcement action is appropriate. EPA will provide written correspondence describing any deficiencies identified during the inspection.

If deficiencies with the Regulations were identified during the inspection and communicated to you during the closing conference you are urged to correct such deficiencies as soon as possible EPA requests you submit all information as soon as possible evidencing your correction of the deficiencies to

Inspector Tom McKay
U S Environmental Protection Agency – Region 6 (6SF PO)
1445 Ross Avenue Dallas TX 75202

If it is not feasible to correct the deficiencies within 30 days of the date of the inspection immediately submit a detailed explanation and schedule indicating by when the noted deficiencies will be corrected. If you believe that your facility is not required to have an SPCC Plan or is in compliance with the SPCC regulatory requirements submit an explanation supported by documentation as to why the facility is not subject to the SPCC provision of the Oil Pollution Prevention regulations at 40 C F R Part 112 or meets its requirements within 30 days of the date of the inspection

Confidential Business Information

For the information submitted to EPA you may be entitled to claim it as Confidential Business Information (CBI) pursuant to the regulations set forth in 40 C F R Part 2 If EPA determines the information you have designated meets the criteria in 40 C F R § 2 208 the information will be disclosed only to the extent and by means of the procedures specified in 40 C F R Part 2 Subpart B Unless CBI is claimed EPA may make the information available to the public without further notice to you

Acknowledgement of Inspection

Signature of Facility Representative

Title of Facility Representative

Warren American Oil Co. 7326 CR # 2420 Barnsdall, OK 74002 918.846.2293

Paul Hopkins

NRC #1144642 160bbls saltwater 10bbls crude

Tank Battery

36. 904 54 -96. 22499 SW10-28-10

Lat. 36.

CR #4190 then CR #4780 off HWY99

1200 Se sorimiens >

